## 大连星镁矿业有限公司 STAR GRACE MINING CO., LTD.

Add: 29-67, No. 929, Xinan Road, Shahekou District, Dalian, Liaoning, China

## **Certificate of Analysis**

**PRODUCT**: MAGNESIUM SULPHATE HEPTAHYDRATE CRYSTAL

THIS IS CERTIFY THAT WE, THE UNDERSIGNED HAVE INSPECTED THE QUALITY OF THE ABOVE MENTIONED GOODS AND FOUND THE RESULT OF INSPECTION AS FOLLOWS:

Test item	Specification	Analysis Results
Purity	99%min	99.51
MgO	16% min	16.18
Mg	9.8%min	9.81
Total S	12%min	12.97
Chloride	0.02%max	0.008
iron	0.001%max	0.0008
As	< 0.0002%	0.0001
Pb	< 0.0005%	0.0001
Particle size (mm)	0.1-1mm	0.1-1mm
Insoluble in the water	0.1%max	0.002
PH	5-7	5.71
Apperance	White crystalline substance	

QUALITY CONTROL DEPT. MANAGER: L. Mai

STAR GRACE MINING CO., LTD. 大连星镁矿业有限公司

Wang xiu zing